

# Buildings and Grounds Report

## October 2019

### Earl Reservoir & Community Center

- Removed all items from inside Pavilion cage and dismantled steel cage walls.
- Dug up all plants bulbs in planters and planting areas.
- Lowered lake about two feet at Earl Rez for lake maintenance.
- Pulled sludge and over grown weeds out of lowered area of lake.
- Dug out mud and dirt around dock to make water level higher for boats.
- Cleaned out leaves around pavilion and play area at the Rez.
- Decorated for Halloween party at Rez.
- Removed decorations post the holiday and used them to decorate other town buildings.
- Cleaned out community center
  - Finished wood trim.
- Installed lighting in parking area around the center.
- Cut down dead ash trees at Earl.

### All Town Buildings/Other Locations

- Painted floors and walls in new enclosed trailer.
- Cleaned all town buildings on a daily basis.
- Maintained town properties.